

PROPERTY LOCATED AT: 30 Merrill St, Portland, ME 04101-3380

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I – WATER SUPPLY

TYPE OF SYSTEM: Public Private Seasonal NA Unknown
 Drilled Dug Other NA

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): N/A Yes No Unknown
Quantity: Yes No Unknown
Quality: Yes No Unknown

If Yes to any question, please explain in the comment section below or with attachment.


WATER TEST: Have you had the water tested? Yes No
If Yes, Date of most recent test: March Are test results available? .. Yes No
To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? Yes No
If Yes, are test results available? Yes No
What steps were taken to remedy the problem? No remediation needed

IF PRIVATE: (Strike Section if Not Applicable):

~~INSTALLATION: Location: NA
Installed by: NA
Date of Installation: NA
USE: Number of persons currently using system: NA
Does system supply water for more than one household? Yes No Unknown~~

Comments: None

Source of Section I information: Seller

Buyer Initials _____ Page 1 of 7 Seller Initials 

PROPERTY LOCATED AT: 30 Merrill St, Portland, ME 04101-3380

SECTION II – WASTE WATER DISPOSAL

TYPE OF SYSTEM: Public Private Quasi-Public NA Unknown


~~IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):~~
Have you had the sewer line inspected?..... Yes No
If Yes, what results: NA
Have you experienced any problems such as line or other malfunctions? Yes No
What steps were taken to remedy the problem? NA

~~IF PRIVATE (Strike Section if Not Applicable):~~
Tank: Septic Tank Holding Tank Cesspool Other: NA
Tank Size: 500 Gallon 1000 Gallon Unknown Other: NA
Tank Type: Concrete Metal Unknown Other: NA
Location: NA ~~OR~~ Unknown
Date installed: NA Date last pumped: NA Name of pumping company: NA
Have you experienced any malfunctions? Yes No
If Yes, give the date and describe the problem: NA

~~Date of last servicing of tank: NA Name of company servicing tank: NA~~
Leach Field: Yes No Unknown
If Yes, Location: NA
~~Date of installation of leach field: NA Installed by: NA~~
~~Date of last servicing of leach field: NA Company servicing leach field: NA~~
Have you experienced any malfunctions? Yes No
If Yes, give the date and describe the problem and what steps were taken to remedy: NA

~~Do you have records of the design indicating the # of bedrooms the system was designed for? Yes No~~
~~If Yes, are they available? Yes No~~
Is System located in a Shoreland Zone? Yes No Unknown
Is System located in a Coastal Shoreland Zone?..... Yes No Unknown

Comments: None
Source of Section II information: Seller

Buyer Initials _____ Page 2 of 7 Seller Initials 

PROPERTY LOCATED AT: **30 Merrill St, Portland, ME 04101-3380**

SECTION III – HEATING SYSTEM(S)/HEATING SOURCES(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S)	Heat Pump / Electric	Radiant / Elec.		
Age of system(s) or source(s)	2017	2017		
Name of company that services system(s) or source(s)	Not needed	Not needed		
Date of most recent service call	NA	NA		
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	See electric bill	See electric bill		
Malfunction per system(s) or source(s) within past 2 years	None	None		
Other pertinent information	None	In Bathrooms		

Are there fuel supply lines? Yes No Unknown

Are any buried? Yes No Unknown

Are all sleeved? Yes No Unknown

Chimney(s): Yes No

 If Yes, are they lined: Yes No Unknown

 Is more than one heat source vented through one flue? Yes No Unknown

 Had a chimney fire: Yes No Unknown

 Has chimney(s) been inspected? Yes No Unknown

 If Yes, date: NA

 Date chimney(s) last cleaned: NA

Direct/Power Vent(s): Yes No Unknown

 Has vent(s) been inspected? Yes No Unknown

 If Yes, date: NA

Comments: **None**

Source of Section III information: **Seller**

SECTION IV – HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? Yes No Unknown

If Yes, are tanks in current use? Yes No Unknown

If no longer in use, how long have they been out of service? NA

If tanks are no longer in use, have tanks been abandoned according to DEP? Yes No Unknown

Are tanks registered with DEP? Yes No Unknown

Age of tank(s): NA Size of tank(s): NA

Location: NA

Buyer Initials _____

Seller Initials  _____

PROPERTY LOCATED AT: **30 Merrill St, Portland, ME 04101-3380**

What materials are, or were, stored in the tank(s)? NA

Have you experienced any problems such as leakage: Yes No Unknown

Comments: None

Source of information: Seller

B. ASBESTOS — Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? Yes No Unknown

In the ceilings? Yes No Unknown

In the siding? Yes No Unknown

In the roofing shingles? Yes No Unknown

In flooring tiles? Yes No Unknown

Other: NA Yes No Unknown

Comments: None

Source of information: Seller

C. RADON/AIR - Current or previously existing:

Has the property been tested? Yes No Unknown

If Yes: Date: NA By: NA

Results: NA

If applicable, what remedial steps were taken? NA

Has the property been tested since remedial steps? Yes No Unknown

Are test results available? Yes No

Results/Comments: None

Source of information: Seller

D. RADON/WATER - Current or previously existing:

Has the property been tested? Yes No Unknown

If Yes: Date: NA By: NA

Results: NA

If applicable, what remedial steps were taken? NA

Has the property been tested since remedial steps? Yes No Unknown

Are test results available? Yes No

Results/Comments: NA

Source of information: Seller

E. METHAMPHETAMINE - Current or previously existing:

Yes No Unknown

Comments: not to seller knowledge

Source of information: Seller

Buyer Initials _____

Seller Initials  _____

PROPERTY LOCATED AT: **30 Merrill St, Portland, ME 04101-3380**

F. LEAD-BASED PAINT/PAINT HAZARDS — (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
..... Yes No Unknown Unknown (but possible due to age)

If Yes, describe location and basis for determination: NA

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: Yes No

If Yes, describe: NA

Are you aware of any cracking, peeling or flaking paint? Yes No

Comments: None

Source of information: Seller

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: Yes No Unknown

LAND FILL: Yes No Unknown

RADIOACTIVE MATERIAL: Yes No Unknown

Other: None

Source of information: Seller

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V — GENERAL INFORMATION

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? Yes No Unknown

If Yes, explain: HOA Documents/Shared Driveway with 5 Cumberland Ave

Source of information: Seller/Deed/HOA Documents

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? Yes No Unknown

If No, who is responsible for maintenance? Association responsible for maintaining parking area

Road Association Name (if known): NA

Buyer Initials _____

Seller Initials  _____

PROPERTY LOCATED AT: **30 Merrill St, Portland, ME 04101-3380**

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....
..... Yes No Unknown

If Yes, explain: **NA**

Is a Forest Management and Harvest Plan available?..... Yes No Unknown
Is house now covered by flood insurance policy (not a determination of flood zone) Yes No Unknown
Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: **NA**

Year Principal Structure Built: **2017**
What year did Seller acquire property? **2018**
Roof: Year Shingles/Other Installed: **2017**

Water, moisture or leakage: **NA**

Comments: **None**

Foundation/Basement:

Is there a Sump Pump? Yes No Unknown
Water, moisture or leakage since you owned the property: Yes No Unknown
Prior water, moisture or leakage? Yes No Unknown

Comments: **None**

Mold: Has the property ever been tested for mold? Yes No Unknown
If Yes, are test results available? Yes No

Electrical: Fuses Circuit Breaker Other: **NA** Unknown

Has all or a portion of the property been surveyed? Yes No Unknown
If Yes, is the survey available? Yes No Unknown

Manufactured Housing – Is the residence a:

Mobile Home Yes No Unknown
Modular Yes No Unknown

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: **None known**

Source of Section V information: **Seller**

Buyer Initials _____

Seller Initials  _____

PROPERTY LOCATED AT: **30 Merrill St, Portland, ME 04101-3380**

SECTION VI – ADDITIONAL INFORMATION

Unit 1 tested for radon and a radon mitigation system was installed in basement in June 2019. New test results showed <.04 pCi/L.

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: Yes No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

DocuSigned by:

12/17/2019
SELLER DATE
Elizabeth Seivering

DocuSigned by:

12/18/2019
SELLER DATE
Hadjh Ahrns

SELLER DATE

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE